



Figure D-65. ARA-II following backfill completion.



Figure D-66. ARA-23 following backfill and contouring.





Figure D-67. ARA-23 looking south toward ARA-II.



Figure D-68. Turnaround area following excavation completion.





Figure D-69. Washdown area during revegetation.



Figure D-70. Reseeding at ARA-23.





Figure D-71. Preparing soils for reseeding.



Figure D-72. Spreading wood chip mulch at ARA-12.





Figure D-73. Turnaround area during revegetation.



Figure D-74. ARA-II during revegetation.